



MONOBOND HIGH ADHESION PRIMER

MONOBOND HIGH ADHESION is a waterborne, urethane acrylic bonding primer and sealer designed for most interior and exterior hard-to-stick surfaces. This high performance primer provides excellent adhesion with fast dry and recoat times allowing projects to be completed quickly and confidently. Monobond High Adhesion can be used on most vertical and horizontal surfaces making it an excellent solution for walls, doors, trim, cabinets, handrails, floors, walkways and much more. Available in a White or Neutral tint base for a full range of color options.

FEATURES:

Excellent Adhesion
Seals Bare Surfaces
Fast Dry & Recoat
Easy-to-Sand
Low Odor & VOC
USDA Compliant

BUILT FOR:

Interior & Exterior
Vertical & Horizontal
Hard-to-Stick Surfaces

Topcoat with Latex,
Alkyd, Epoxy, or
Urethane Finishes

BEST ON:

Concrete, Masonry,
Stucco, & Asphalt
Wood & Composite
Non-Ferrous Metal
Fiberglass & Plastic
Tile & Glass
Kynar & Vinyl
Previous Paint

MEETS VOC REQUIREMENTS:

CAL Green	YES
SCAQMD	YES
CARB	YES
National AIM	YES
Green Seal GS-11	YES
LEED v4 v5	YES

SPECIFICATIONS:

Composition:	Waterborne Urethane Acrylic
VOC (ASTM D6886):	< 100 g/L
Solids by Weight:	White 52% $\pm$ 2 Neutral 34% $\pm$ 2
Solids by Volume:	White 38% $\pm$ 2 Neutral 31% $\pm$ 2
Shelf Life:	2 Years

AVAILABLE PRODUCTS:

MFG Codes:	1990 White 1980 Neutral
Finishes:	White - Flat Neutral - Gloss
Tint Capacity: <i>Waterborne Colorants</i>	White - 0-2 oz / gal Neutral - 4-6 oz / gal
Sizes:	1 Gallon, 5 Gallon

***Neutral Base can be used as a Clear Primer*

PREPARATION:

All surfaces must be cured, firm and dry. Use suitable cleaning methods to remove all dirt, efflorescence, oil, rust, or other contamination. To maximize adhesion, sand smooth, glossy, dense, or glazed surfaces to create a profile and remove dust (See **WARNING!**)

APPLICATION:

Brush:	Synthetic Bristle
Roll:	Synthetic Nap - 1/4" - 3/8"
Spray:	2000 PSI; 0.009" - 0.015" Tip

Temperature:	40°F - 90°F Air, Surface, & Material
Film Thickness:	3-5 Wet Mils 1.5-2 Dry Mils
Coverage:	250-400 Sq. Ft. / Gal
Drying Time: @75°F; 50% R.H.	30 Minutes Dry-to-Touch 2-3 Hours Recoat <i>Topcoat within 24 Hours</i>
Thinning:	Not Recommended
Clean Up:	Water

Primer – 1 Coat:

Monobond - High Adhesion Primer

Topcoat – 2 Coats:

Monochem Product or Similar Latex or Alkyd

All Surfaces:

Recoat or topcoat after 2-3 hours and within 24 hours. If 24 hours has been exceeded, reprime or sand the surface to ensure adhesion.

Application Guidance: Information provided is a general guide based on standard substrates and conditions. Jobsite conditions, environment, and application methods may affect product performance. Always perform a test sample before full application to confirm suitability. If results do not meet project requirements, contact a Monopole representative before proceeding.

See following pages for detailed preparation and application instructions.





MONOBOND HIGH ADHESION PRIMER

PREPARATION & APPLICATION:

BEFORE APPLICATION

GENERAL PREPARATION: All surfaces must be cured, firm, dry and cleaned free of dust, dirt, oil, grease, wax, chalk, rust, mildew or any other contamination or condition that would adversely affect the performance of the coating. Mechanically grind or sand glossy, dense or glazed surfaces (see **WARNING!**). Protect all surrounding areas - shrubbery, plants, grass, glass, metal, glazed surfaces, etc.

REPAIRS: Complete any required structural or substrate repairs prior to application and allow repair materials to fully cure. Ensure horizontal surfaces have positive drainage or slope (minimum 1/4" per foot) to eliminate ponding water.

PATCHING & CAULKING: Fill and seal any voids, seams, holes, or cracks greater than 1/16" using an appropriate paintable patching material and allow to fully cure. Spot priming patched areas is recommended. Coating over flexible patch or caulking or in areas with substrate movement may cause the topcoat to crack.

MOISTURE: Ensure roofs, windows, doors, and all penetrations are properly installed, sealed, and caulked to prevent moisture intrusion. All surfaces must be dry before application. Properly seal all sides of the surface to keep moisture out. Moisture intrusion behind the coating may cause blistering or peeling.

CONCRETE & MASONRY: All surfaces must be thoroughly cured and have an adequate profile. Curing compounds, non-recoatable sealers, and densifiers must be removed or properly primed. Moisture content must be < 15% and pH < 8. Calcium chloride testing moisture testing is recommended per ASTM F1869.

WOOD: All surfaces must be unsealed and porous or properly primed. Moisture content must be < 13%. Allow tannin-rich wood to weather until tannins naturally come out of the substrate. Clean tannins from surface. If needed, apply a tannin resistant stain blocking primer prior to painting.

METAL: Remove all loose rust, mill scale, or deteriorated previous coatings by Hand Tool (SSPC-SP-2) or Power Tool (SSPC-SP-3) cleaning. Wash surface with a suitable cleaner or degreaser to remove oil and contaminants and allow to dry. Prime ferrous metal with a rust preventative primer as soon as it dries.

PREVIOUSLY PAINTED SURFACES: Remove any peeling, chalky or loose paint, sand to feather edges, and dust clean. Spot prime bare and patched areas. When making a significant color or sheen change, a primer is recommended to aid hide and appearance of the topcoat.

STAIN BLOCKING: When painting over stains or tannins, an appropriate stain blocking primer is recommended before painting.

MIXING: Mix well before use. Purchase enough material to complete your project at the same time. If additional material is needed, retain some of the original material and intermix before application or touch up.

CONTAINERS AND TOOLS: Transfer material into a clean container for use. Use new or thoroughly cleaned tools. To avoid contamination, do not re-dip applicators or add used material into the storage containers.

DURING APPLICATION

TESTING: Prior to full application, complete the preparation and apply a test patch to ensure the system chosen is appropriate for the project. If results do not meet expectations, contact Monopole Inc. for recommendations.

GENERAL PAINTING: Primer or sealer is always recommended prior to painting. Apply two separate finish coats to create even color, uniform sheen, maximum durability and easier touch-up. Maintain a wet edge while painting.

WEATHER: Apply product only when material, air, and surface temperature are within the recommendations on page 1 and will remain within that range for at least 24 hours. Temperatures must remain 5° above the dew point during application and dry time. Do not expose to rain, fog, snow or any moisture during application or dry time. Limit exposure to heavy moisture for 24-48 hours after application.

COVERAGE: May vary depending on method of application, porosity and texture of the surface. Measure estimated coverage during the test application.

FILM THICKNESS: Always follow recommendations for application thickness on page 1. Over application may reduce performance and can lead to runs, extended dry times, a soft film, cracking, or a white haze (clear coatings).

BACKROLLING: While spraying, it is recommended to follow with a wet roller to ensure an even coat and fill in porous surfaces. This will reduce pinholes, create uniform sheen and make for easier touch-up.

RECOATING: Always follow recommendations for recoat times on page 1. Recoating too soon or too long after application may reduce performance and lead to adhesion loss, improper cure or a soft film.

AFTER APPLICATION

DRYING: Dry times are based on standard conditions of 75°F with a relative humidity of 50%. Lower temperatures or higher humidity may extend drying times. Higher temperatures may speed up drying time and shorten pot life. Provide adequate ventilation and air movement during and after application.

STORAGE: Store material at room temperature in clean, tightly sealed containers free of rollers, brushes, or other outside materials. Protect from freezing.

CURE: Coatings may require between 7-30 days after final application for full cure and maximum performance. Cure times vary depending on application and environmental conditions.

CLEANING: Wait until at least two weeks after final application to clean contaminants from the surface. Use fresh water and a small amount of mild detergent or non-solvent cleaner, if necessary. If power washing, use low pressure or wide fan tips to maintain the integrity of the coating.

WARNING! If you scrape, sand or remove old paint from any surface, you may release lead dust. LEAD IS TOXIC. EXPOSURE TO LEAD DUST CAN CAUSE SERIOUS ILLNESS, SUCH AS BRAIN DAMAGE, ESPECIALLY IN CHILDREN. PREGNANT WOMEN SHOULD ALSO AVOID EXPOSURE. Wear a NIOSH approved respirator to control lead exposure. Carefully clean up with a wet mop or HEPA vacuum. Before you start, find out how to protect yourself and your family by contacting the U.S. EPA/Lead Information Hotline at 1- 800-424-LEAD (5323) or log on to www.epa.gov/lead.

WARRANTY: The statements made on this bulletin, product labels or by any of our agents concerning this material are given for information only. They are believed to be true and accurate and are intended to provide a guide to approved construction practices and materials. As workmanship, weather, construction equipment, quality of other materials and other variables affecting results are all beyond our control, Monopole, Inc., does not make nor does it authorize any agent or representative to make any warranty of MERCHANTABILITY OR FITNESS for any purpose or any other warranty, guarantee or representation, expressed or implied, concerning this material except that it conforms to Monopole, Inc.'s quality control standards. Any liability whatsoever of Monopole, Inc. to the buyer or user of this product is limited to the purchaser's cost of the product itself.

